

**Application:** Mould Injection

**Product Group:** Filtration & Sai



**Summary:** The customer had a complaint that the life of the Sai motor was not long. Upon further investigation it was found that the system was highly contaminated and causing wear, in turn reducing the life of the motor.

**Solution:** Put filtration in the system, pressure & return resulting in cleaner oil, less wear on the motor and less down time.